Quick Setup Guide

Charge Battery → **Caution: Use supplied charger only** → **Connect charger AC power cord to AC outlet** → **Connect DC plug to socket on side of 831** → → **Full charge in approximately 2.5 hours**

Power On / Off → → `Model 831` / `WWW.METONE.COM` → `PM2.5 50.3 µg` / `PM10 112.7 µg`

Take a sample → → `PM2.5 50.3 µg` / `PM10 112.7 µg` → **Display other ranges** → ROTATE → `PM2.5 50.3 µg` / `PM1 112.7 µg`

View settings → PRESS → `Rotate and Press` / `LOCATION 001` → ROTATE → **See Settings Table (other side)** → **Return to Sample Screen** → Or, wait 5 sec.

Change settings → PRESS → ROTATE → **See Settings Table (other side)** → PRESS → **ROTATE / PRESS to change values** → **Cancel changes** →

Transfer data → **Attention: Install serial driver CD before connecting USB cable** →

→ **Install and run Comet to transfer data**
→ **See Serial Commands Table (other side)**